



\leq

#2












SouthwestSolutions.com | 1-800-803-1083

3


Recommend wood studs Blocking can span over the existing studs or in between existing studs If metal studs, make sure the blocking spans the metal studs












 $\begin{pmatrix} 1 & 1 \\ 1 & 1 \end{pmatrix}$

WOOD STUD DRY WALL





Locate Stud

Mark Center Line

Wall Mounted Seat Residential Assembly Instructions


WOOD STUD DRY WALL







3


2







Wall Mounted Seat Residential Assembly Instructions





WOOD STUD DRY WALL







6

SouthwestSolutions.com | 1-800-803-1083

7